


UNIT POLE		WATCH LINE	
(REG. N 64°50'00" E	85.00)	(BEARING	BASIS)
N 64°50'00" E	85.00	N 64°50'00" E	107.00



	1/2" IRON PIPE FOUND
	1/2" REBAR FOUND
	1/2" REBAR SET
	600 NAIL FOUND
	600 NAIL SET
	SPINDLE FOUND
	BARBED WIRE FENCE
	CHAIN LINK FENCE
	WOOD FENCE
	METAL FENCE
	BUILDING LINE
	PUBLIC UTILITY EASEMENT
	DRAINAGE EASEMENT
	SURFACE DRAINAGE EASEMENT
	ELECTRIC EASEMENT
	WATER/WASTEWATER
	RECORD INFORMATION
	POWER POLE
	OVERHEAD UTILITIES

DATE 12/18/03
TITLE CO LONGHORN
D.F. / 2421000821
JOB / 12-018-03
SCALE 1:20

I DO HEREBY CERTIFY TO THOSE LISTED HEREON THAT THE SLURRY WAS THIS DAY MADE ON THE GRADING UNDER MY SUPERVISION, AT THE PROPERTY LEGALLY DESIGNATED HEREON, IS PREPARED IN ACCORDANCE TO THE TITLE COMMITMENT REFERENCED HEREON, AND THAT THERE ARE NO VISIBLE BOUNDARY LINE CONFLICTS, ENCROACHMENTS OR COLLAPSE OF IMPROVEMENTS, OR OBSTACLES IN PLACE, EXCEPT AS SHOWN HEREON, TO THE BEST OF MY KNOWLEDGE. ONLY DOCUMENTS CONTAINED WITHIN THE APPROPRIATIONS TITLE COMMITMENT WERE REVIEWED.

THIS AREA IS DEPICTED AS BEING IN A SPECIAL
FLOOD HAZARD AREA PER FEMA'S FLOOD INSURANCE
RATE MAP 410894 0210 F. DATED 11/01/91. IT IS
REPRESENTED AS IN ZONE AE. HOWEVER, AT PRESENT
TIME, NO ELEVATION DATA OR STUDIES HAVE BEEN
PERFORMED AND INFORMATION IS BASED
ON EVIDENCE UPON SAID MAP. THE SURVEYOR DOES NOT
WARRANT RESPONSIBILITY AS TO ANY INFORMATION
CONTAINED BY SAID MAP AND DOES NOT IMPLY THAT THE
PROPERTY AND/OR THE STRUCTURES THEREON WILL BE
IN A STATE OF FLOOD DAMAGE. FOR FURTHER INFORMATION
CONTACT YOUR FLOOD PLAIN ADMINISTRATOR.

TO THE LONGHORN MAB / ON THE ORDER OF THE PROMOTER FURNISHED AND TO
MILITONE MORTGAGE CORPORATION / LONGHORN TITLE COMPANY

DECLASSIFIED	JA	12-16-03
FIELD WORK	JL	12-16-03
DISPATCH	WYLE	12-16-03
FINAL CHECK		12-16-03
COMPLETION		
UP DUTY		