ELITE RESTORATION

Elite Restoration

1920 Highland Ave E. Twin Falls, ID 83301 www.Elite-Restoration.com

Client: Triple A Reality Home: (208) 280-1380 Property: 3348 Highlawn dr. Twin Falls, ID 83301 Operator: **DANIE Estimator: Daniel Sholes** Business: (208) 220-4080 Position: Estimator E-mail: daniels@elite-restoration. com Company: Elite Restoration **Business:** 1920 Highland Ave E Twin Falls, ID 83301 Type of Estimate: Mold Remediation Date Entered: 7/22/2025 Date Assigned: Price List: IDTF8X JUL25 Labor Efficiency: Restoration/Service/Remodel Estimate: TRIPLEA-T255-MLD File Number: T25-255-MLD Thank you for choosing Elite Restoration for your Mold Remediation needs. Listed within this estimate you will find a detailed description of the requested proposed scope of work. The line item pricing in this estimate does not represent the actual cost of goods or services. Pricing for this project is based on the entire scope of work and may change due to any modifications of the scope, quality or scheduling constraints. Any changes to this original estimate including but not limited to material upgrades, code requirements, and hidden or unforeseen damages will be included in a separate estimate unless otherwise noted. By signing below the above said customer Triple A Reality acknowledges and is in agreement with the scope of work for the Grand Sum Total of: (\$6,559.64). A finance charge of 1.5% per month (minimum of \$1.00) will be applied to any unpaid balance after thirty (30) days of completion of work. Any exceptions must be approved by Elite Restoration's General Manager. All PROPOSALS require a 50% deposit prior to start of work, unless otherwise approved prior to acceptance. Customer Signature:

Elite Restoration is a full service restoration contractor specializing in residential and commercial property mitigation, content cleaning, and damage repair services.

Elite Restoration: _____



1920 Highland Ave E. Twin Falls, ID 83301 www.Elite-Restoration.com

Idaho Contractors # RCE 28623



1920 Highland Ave E. Twin Falls, ID 83301 www.Elite-Restoration.com

TRIPLEA-T255-MLD

TRIPLEA-T255-MLD

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Emergency service call					
Emergency service call - during business hours	1.00 EA	0.00	229.97	0.00	229.97

Includes: Administrative/labor costs associated with allocating resources for an emergency response during normal business hours as needed. Excludes: All labor, travel, materials, or equipment to do the work. Add the appropriate water extraction item code for the work being done. Note: An emergency service charge is representative of costs resulting from the immediate reassigning of employees from a job in progress or the activation of employees from on-call status for emergency response. Some areas may charge a higher rate for evening hours or a premium rate for holidays (see WTR ESRV for after-hours service). Whether a situation warrants an emergency response will need to be determined by those involved.

PPE

Total: TRIPLEA-T255-MLD				5.89	335.59
4. Respirator - Half face - multi- purpose resp. (per day)	1.00 DA	0.00	1.67	0.00	1.67
3. Respirator cartridge - HEPA only (per pair)	1.00 EA	0.00	18.44	1.11	19.55
2. Add for personal protective equipment - Heavy duty	2.00 EA	0.00	39.81	4.78	84.40
					

Attic

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Protection / Containment					
5. Floor protection - cloth - skid resistant, leak proof	20.00 SF	0.96	0.00	0.47	19.67
Labor Trade updated to CLN-R to refle	ect actual conditions.				
Antimicrobial					
6. Clean the surface area - Heavy	2,025.00 SF	0.00	0.63	1.22	1,276.97
7. Apply mold/mildew stain remover to the surface area	2,025.00 SF	0.00	0.90	37.67	1,860.17
8. HEPA Vacuuming - Detailed - (PER SF)	2,025.00 SF	0.00	1.12	0.00	2,268.00
9. Add for HEPA filter (for canister/backpack vacuums)	1.00 EA	0.00	97.13	4.65	101.78
Totals: Attic				44.01	5,526.59

Crawlspace

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL

Protection / Containment



1920 Highland Ave E. Twin Falls, ID 83301 www.Elite-Restoration.com

CONTINUED - Crawlspace

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
10. Floor protection - cloth - skid resistant, leak proof	20.00 SF	0.96	0.00	0.47	19.67
Antimicrobial					
11. Clean the surface area - Heavy	22.50 SF	0.00	0.63	0.01	14.19
12. Apply mold/mildew stain remover to the surface area	22.50 SF	0.00	0.90	0.42	20.67
13. HEPA Vacuuming - Detailed - (PER SF)	22.50 SF	0.00	1.12	0.00	25.20
14. Add for HEPA filter (for canister/backpack vacuums)	1.00 EA	0.00	97.13	4.65	101.78
Totals: Crawlspace				5.55	181.51

Equipment

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL			
Drying Equipment - Equipment used to Mitigate the structure and return it to rebuild able condition.								
Equipment Labor								
15. Equipment Setup (hourly charge)	0.50 HR	0.00	82.92	0.00	41.46			
Set up - 15 Minutes per Piece of equipmen	nt							
16. Equipment Take down (hourly charge)	0.50 HR	0.00	82.92	0.00	41.46			
Take Down - 15 Minutes per Piece of equ	ipment							
Equipment								
17. Air mover (per 24 hour period) - No monitoring	1.00 EA	0.00	31.00	0.00	31.00			
18. Negative air fan/Air scrubber (24 hr period) - No monit.	1.00 DA	0.00	80.57	0.00	80.57			
19. Add for HEPA filter (for negative air exhaust fan)	1.00 EA	0.00	214.54	11.77	226.31			
Equipment Cleaning & Disinfecting								
20. Equipment decontamination charge - per piece of equipment	2.00 EA	0.00	47.23	0.69	95.15			



1920 Highland Ave E. Twin Falls, ID 83301 www.Elite-Restoration.com

CONTINUED - Equipment

DESCRIPTION QTY REMOVE REPLACE TAX TOTAL

Includes: Charge for wiping down equipment, germicide, and labor.

Note: Labor cost to wash/wipe down contaminated equipment that can easily be removed with moderate scrubbing and/or minimal cleaning. Per piece of equipment.

Mitigation contractors are required to take additional decontamination steps for each piece of equipment placed within a project after completion. Air moving devices inherently tend to aerosolize soils and particulate present in the environment. as water evaporates from surfaces and materials such as carpet, more particles often become aerosolized and due to this all equipment needs to cleaned after the restorative drying process is completed.

Reference: IICRC S500 3rd Edition standards.

IICRC S500 12.3.2 - "Restorers should ensure that contaminated equipment is cleaned and decontaminated, or contained prior to moving through unaffected areas, transported, or used on subsequent jobs."

IICRC S500 12.3.3 - "Tools and equipment should be cleaned and decontaminated, or contained on the job site before being loaded for transport away from the site."

Totals: Equipment	12.46	515.95

ELITE RESTORATION

Elite Restoration

1920 Highland Ave E. Twin Falls, ID 83301 www.Elite-Restoration.com

Summary

Line Item Total Material Sales Tax		6,491.73 67.91
Replacement Cost Value Net Claim		\$6,559.64 \$6,559.64
	Daniel Sholes Estimator	



1920 Highland Ave E. Twin Falls, ID 83301 www.Elite-Restoration.com

Recap of Taxes

	Material Sales Tax (6%)	Manuf. Home Tax (6%)	Storage Tax (6%)
Line Items	67.91	0.00	0.00
Total	67.91	0.00	0.00



1920 Highland Ave E. Twin Falls, ID 83301 www.Elite-Restoration.com

Recap by Room

Estimate: TRIPLEA-T255-MLD	329.70	5.08%
Attic Crawlspace	5,482.58 175.96	84.45% 2.71%
Equipment	503.49	7.76%
Subtotal of Areas	6,491.73	100.00%
Total	6,491.73	100.00%



1920 Highland Ave E. Twin Falls, ID 83301 www.Elite-Restoration.com

Recap by Category

Items	Total	%
CLEANING	1,289.93	19.66%
GENERAL DEMOLITION	38.40	0.59%
HAZARDOUS MATERIAL REMEDIATION	4,330.21	66.01%
WATER EXTRACTION & REMEDIATION	833.19	12.70%
Subtotal	6,491.73	98.96%
Material Sales Tax	67.91	1.04%
Total	6,559.64	100.00%

Xactware does not warrant the accuracy of pricing information in the Price Data. Price Data are intended to be a representation of historical information to be used as a baseline or place to begin creation of an estimate. You are responsible to ensure the estimate includes pricing consistent with components including but not limited to actual materials, equipment, and labor pricing. You acknowledge and understand that Price Data provided as part of the Services are intended to target the most representative price of the various price points collected relevant to the specific line item in question. Having this single representative price per line item, computed from all valid price points researched in the market, means that some market price data are higher, and some market price data are lower than that which are reported. You agree not to prohibit or preclude deviations from the Price Data where contractor requirements, market conditions, demand or any other factor warrants the use of a different line item price in the specific situation.